Planned Maintenance Programme			
Property ID	Work element needed	Area	DEPT
	Basement area walls showing	Area	DEPT
	signs of water ingress to several		
	areas further investigation		
	required following repairs a		
City Hall	complete redecoration of all	Central	P&P
City Hall	Repair all basement doors/	Central	P&P
	Redecorate all previously		
Church Lane PC	painted surfaces to male toilets	Central	HES
City Hall	Internal touch up	Central	P&P
City Hall	Block up openings in basement	Central	P&P
	Clock Maintenance - Canavan		
Albert Clock	Clockmakers	Central	P&P
City Hall	City Hall Goods Lift Replacement	Central	P&P
City Hall	Fit auto door closers 6pr	Central	P&P
City Hall	Repaint LMP	Central	P&P
	Refurbishment of Bothy		
	including internal redecoration,		
	partial rewire, replacement		
	switchgear, fire alarm upgrade,		
Dunbar Street Cleansing Depot	and boiler replacement & HWST	Central	HES
	Re-lable Fixed Wiring &		
Adelaide Exchange	Emergency lighting	Central	P&P
	Fire alarm need upgraded to		
	BS5839 fire alarm cables tied		
Cecil Ward Building	with plastic cable ties	Central	P&P
Cecil Ward Building	Minor leaks to Atrium roof	Central	P&P
City Hall	Pea lights - Trees	Central	P&P
Cecil Ward Building	Fitting handrails to roof of	Central	P&P
	Fire alarm requires Auto		
	Detection in the CMMS rooms.		
Adelaide Exchange	Intruder alarm is never Set.	Central	P&P
City Hall	Christmas Installation	Central	P&P
Roselawn Cemetery - Office	Alterations to managers office	East	P&L
	Refurbishment of staff canteen		
Roselawn Crematorium	& toilets H&S	East	P&L
O-Zone/Tennis Centre	Install climbing wall cameras	East	P&L

	Carryout Redecoration of All		
Avoniel Play Centre	Previously Painted Surfaces	East	DEV
	Carryout Redecoration of All		
ATP Memorial Park - Bowling	Previously Painted Surfaces		
Pavilion	both internally and Externally.	East	P&L
	Main Sports Hall Recommend		
Avoniel Leisure Centre	redecoration	East	P&L
Avoniel Leisure Centre	Roller shutters require	East	P&L
Blanchflower Playing Fields -	External redecoration of all		
Changing Pavilion	previously painted surfaces	East	P&L
Orangefield Park - Bowling	Fence railings require repairs		
Pavilion	and redecoration.	East	P&L
	Cremator Room Carryout		
	Redecoration of All Previously		
Roselawn Crematorium	Painted Surfaces both internally	East	P&L
Roselawn Crematorium	Redecorate Basement and café	East	P&L
	External Redecoration to all		
Dundonald Cemetery - House	previously painted fascia and	East	P&L
	Redecorate all external		
	palastraid fencing and steel fire		
	escapes to building. Carryout		
Ballymacarrett RC	repairs to brickwork soldier	East	P&L
	New timber floor finish to		
	changing room corridor repaint		
Ballymacarrett RC	floor tiles to male toilets and	East	P&L
Roselawn Crematorium	Refurbishment of crematory	East	P&L
	Modify Ramp, road marking,		
ATP Memorial Park - Changing	signage, contrast & Handrails as		
Pavilion	per DDA report.	East	P&L
Blanchflower Playing Fields -	High Fail Rate of Fittings		
Changing Pavilion	throughout building refurb of	East	P&L
	DDA upgrade Signage, Ramps,		
	colour contrast of décor, &		
Knocknagoney Community Cent	Lower sanitary ware	East	DEV
	Poor water Pressure in places		
Roselawn Crematorium	consider installing a booster	East	P&L
Dundonald Cemetery - Office	Refurbishment of office	East	P&L
Dee Street Community Centre	Mat store smoke extract system	East	DEV

	Timber Cladding is damaged & in		
	poor condition renew damaged		
Duncrue Complex - Vehicle	sections and redecorate all		
Wash Facility	previously painted surfaces	North	HES
	Timber cladding rotting patch		
Waterworks - Social Pavilion	repair and redecorate	North	P&L
	Fascia in poor condition		
Shore Road Playing Fields -	carryout prepaint repairs and		
Old Changing Pavilion	Redecorate all previously	North	P&L
Duncrue Complex - Main			
Building	Refurbisment of Bothy	North	HES
Belfast Zoo - Farm & School	farm• Complete work to hand		
house	washing/drying facilities;	North	P&L
COBFP - Bothy	Refurbishment	North	P&L
Grove Playing Fields - Bothy	Refurbishment	North	P&L
	Pre paint repairs required to all		
	fascia & Soffit boarding and		
Ballysillan Leisure Centre	Complete redecoration of all pre	North	P&L
	External Fence required		
COBGC - Clubhouse	Redecoration to all surfaces	North	P&L
	Carryout a complete internal		
Shore Road Playing Fields -	redecoration of all previously		
Old Changing Pavilion	painted surfaces	North	P&L
Shore Road Playing Fields -	All Quary floor tiles throughout		
Old Changing Pavilion	require a deep clean	North	P&L
Belfast Castle	Painting backstair case	North	P&L
Belfast Castle	Internal touch up	North	P&L
	Back of house Wall & Ceiling		
	decoration very poor		
Belfast Castle	Redecoration required of all	North	P&L
Belfast Castle	Vinyl replacement back of house	North	P&L
Duncrue Complex - Main	Porch area to transport and		
Building	waste collection offices	North	HES
	Provide break tank to		
Belfast Zoo - Administration	incomming water supply to		
Building	isolate from NI Water Main	North	P&L
	Provide break tank to		
	incomming water supply to		
Belfast Castle - Pump House	isolate from NI Water Main	North	P&L
Belfast Castle	Refurbishment of ground floor	North	P&L

Belfast Castle	Painting stairwell	North	P&L
	Complete redecoration of all		
Duncrue Complex - Security	previously painted surfaces		
Office	both internal and Externaly	North	HES
	All old switch start fluorescent		
Duncairn Community Centre	lights to be replaced	North	DEV
	No emergency lighting in ground		
Duncairn Community Centre	floor male toilet	North	DEV
	Electrical Heating not working in		
COBGC - Clubhouse	areas throughout the building	North	P&L
Belfast Zoo - Main House	Earth Rod & RCD'S required at	North	P&L
	DDA upgrade Marking out,		
	Signage, Entrance Alterations,		
Highfield Community Centre	colour contrast of décor, &	North	DEV
	Complete upgrade of Communal		
	Kitchen units		
Highfield Community Centre	repair/replacement as per Client	North	DEV
Belfast Zoo - Administration			
Building	Perimeter fence completion	North	P&L
	LED Lamps throughout (&		
Belfast Castle	dimming system review)	North	P&L
	Upgrade of Marking out,		
Belfast Castle	Signage Colour Contrast,	North	P&L
	Parks Bothy Canteen area		
	requires complete redecoration		
Belfast Castle	of all previously painted	North	P&L
Belfast Castle	Up grade 1st floor toilets	North	P&L
Waterworks - Social Pavilion	Redundant Sub Mains to be	North	P&L
Alexandra Park Service Yard	No Evidence of Mains Earth	North	HES
Duncrue Complex - Security	Recommend complete rewire of		
Office	building	North	HES
Dargan Road Landfill Site -	Fire Alarm installation required		
Office/Weighbridge	to office weighbridge	North	HES
Belfast Zoo - Administration	Repairs arising from Playground		
Building	Playground Report MW	North	P&L
Ballysillan Leisure Centre	Boiler Flue Replacement	North	P&L
	No emergency lighting within		
COBFP - Bothy	this building	North	P&L
COBFP - Bothy	No Fire alarm within this	North	P&L
Waterworks - Bothy	Replace fence around slit traps	North	P&L

Cherryvale Playing Fields -	Grounds. Small fence at		
Changing Pavilion	playground H&S	South	P&L
	WIRES Report. Paint is peeling		
	off the railings surrounding		
	the play area. While also		
Donegal Pass Community	looking unsightly, the paint		
Centre	chippings are falling and lying	South	DEV
	Service Yard outbuildings		
Musgrave Park - Bothy	require major refurbishment of	South	P&L
	Internally repair damage plaster		
	to main hall and redecorate		
Finaghy Community Centre	allpreviously painted surfaces	South	DEV
	WIRES Report. Water and		
	sludge is running off the roof		
	area just directly external to		
	the Sure Start room. This area		
	is where the young babies and		
	children play. It is		
	recommended that some form		
Donegal Pass Community	of a drip tray, or pipe is		
Centre	attached to the roof area to	South	DEV
	WIRES Report • signage on the		
	roller shutter to ensure that		
	unauthorized persons do not		
	entre this area (e.g. no		
Morton Community Centre	unauthorised persons beyond	South	DEV
King William Park	Paint railings	South	P&L
-	Carryout Redecoration of All		
Finaghy Community Centre	Previously Painted Surfaces	South	DEV
	Carryout Redecoration of All		
Cherryvale Playing Fields -	Previously Painted Surfaces		
Changing Pavilion	both internally and Externally.	South	P&L
Boucher Road Playing Fields -	Handrails and steps throughout		
Changing Pavilion	require redecoration to DDA	South	P&L
Boucher Road Playing Fields -	Complete Redecoration of all		
Changing Pavilion	internal and external areas	South	P&L
	WIRES REPORT The area in the		
	vehicle loading bay Please		
	ensure that steps are taken to		
Morton Community Centre	make this area safer, such as:	South	DEV

Malone House	Internal touch up	South	P&L
Malone House	Paint main staircase	South	P&L
Malone House	Internal painting, main rooms	South	P&L
	Painting of external Fascia		
O-Zone/Tennis Centre	boards Doors and Frames	South	P&L
	WIRES Report All distributor		
	boards, isolator switches etc.		
	clearly marked and access		
	restricted		
	Please liaise with Property		
	Maintenance Unit electrical		
	team to see that if the location		
	of the mains distribution board		
	meets the requirements of 17th		
	Edition IEE Wiring Regulations. If		
	it does not meet the required		
Olympia Community Centre	standard please ensure that the	South	DEV
	Existing Ventilation in showers is		
	inadequate, (no vent in toilets		
Boucher Road Playing Fields -	blocks) Install new wall		
Changing Pavilion	mounted extraction fans.	South	P&L
Cherryvale Playing Fields -	Recommend replacement of all		
Changing Pavilion	old light fittings on 1st floor	South	P&L
	LED Lamps throughout (&		
Malone House	dimming system review)	South	P&L
	DDA upgrade Signage, colour		
	contrast of décor, Handrails,		
Malone House	install a ramp & Provide	South	P&L
	Up grade existing glazed area		
Malone House	towards toliets, including roof.	South	P&L
Malone House	Vinyl replacement back of house	South	P&L
	Reinstatement of Collapsed		
Drumglass Park - Bothy	Boundry Wall	South	P&L
Ormeau Park - Bowling	Grounds. Paint 578mts railings		
Pavilion (Ormeau Rd)	H&S and ASB	South	P&L
	Midgely Park / Olympia Leisure		
	Centre Erect new Perimeter		
Olympia Leisure Centre	Fence to Midgely Street	South	P&L

	Carryout a complete		
	refurbishment of The boxing		
North Queen Street	Club Changing & shower room		
Community Centre	and redecorateall previously	West	DEV
	Fascia to North elevation renew		
Whiterock Leisure Centre	and redecorate	West	P&L
	WIRES Report Remove the eye		
	level cupboards in this area to		
	ensure that steam from the		
	boiler is allowed to escape		
Horn Drive Community Centre	upwards away from people's	West	DEV
	WIRES Report Please ensure		
	that appropriate directional		
	signage is provided in the areas		
	identified to make centre users		
Horn Drive Community Centre	aware of the direction of the	West	DEV
Falls Park -Service Yard	Replace kitchen	West	P&L
	Internal repairs and		
	redecoration works required to		
	- Ground Floor - Entrance Hall,		
	Male & female Dry Changing,		
	Sauna & Shower area Male staff		
	changing -First Floor - Poolside		
	Wall finishes, Male & female wet		
Shankill Leisure Centre	changing, Poolside Wet	West	P&L
	Village Changing Area - Change		
	stud partition to Fermacell		
	backboard or other similar		
Falls Leisure Centre	(Tiling backboard is rotting at	West	P&L
North Queen Street Play Centre	Build new disabled to rear of	West	P&L
Andersonstown Leisure Centre		West	P&L
Woodvale Park - Bothy	Refurbishment	West	P&L
North Queen Street	Replace showers in the boxing		
Community Centre	club area	West	DEV
Ardoyne Community Centre	Internal / External painting	West	DEV
	Renew sections of facia as		
	required and redecorate all		
Horn Drive Community Centre	fascia and Soffit also all external	West	DEV

	Complete redecoration to all		
Falls Leisure Centre	function rooms	West	P&L
	WIRES Report The exterior fire		
	escape route that leads away		
	from the fire escape stairs is		
	over very poor and uneven		
	ground conditions. This also		
	leads the other direction as		
	access to the plant room used		
	by staff and contractors. In the		
	current condition a tripping		
	hazard is likely. Regulation 12(2)		
	of the Workplace Health Safety		
	and Welfare Regulations (NI)		
	1993 requires that traffic		
Hammer Community Centre	routes, shall not be uneven or	West	DEV
	WIRES Report Have the		
	installation of the wall mounted		
	boiler completed thus removing		
Horn Drive Community Centre	the need to use the free	West	DEV
	WIRES Report Electrical store		
	cupboard to be labelled with		
Horn Drive Community Centre	high voltage warning signs	West	DEV
Divis Community Centre	External painting	West	DEV
	WIRES Report It is		
	recommended that contact is		
	made with Property		
	Maintenance Unit in Duncrue to		
Sandy Row Community Centre	seek a solution to the trip	West	DEV
	Lightening Conductor requires		
Andersonstown Leisure Centre		West	P&L
	Fire alarm cabling secured with		
	plastic cable ties. And Fault with		
Falls Leisure Centre	Fire alarm EVAC	West	P&L
	Pool earth bar corroded cabling		
Falls Leisure Centre	and containment corroded	West	P&L
Falls Leisure Centre	70 Faults with Emergency light	West	P&L
	Emergency Lighting system		
Sandy Row Community Centre	requires a upgrade all areas	West	DEV

	Existing Fire alarm requires an		
Sandy Row Community Centre	upgrade of the complete system	West	DEV
	As per DDA audit Resurfacing of		
	pathways fitting of Automatic		
	access doors signage and		
Agnes Street PC	redecoration to DDA colour	West	P&P
	DDA upgrade, Signage, alter		
Sandy Row Community Centre	sanitary ware	West	DEV
	Renew floor covering to both		
	sports halls also renew flooring		
Sandy Row Community Centre	to committee room	West	DEV
	DDA audit Recommendations		
	Ramped access, Automatic Door		
Agnes Street Civic Amenity	entry, Signage fitting of		
Site	Handrails and upgrade of	West	HES
Andersonstown Leisure Centre	Refurb handball court, floor and	West	P&L
Falls Leisure Centre	Up grade gents toilets pool side	West	P&L
Whiterock Leisure Centre	Refurb male /female changing	West	P&L
Andersonstown Leisure Centre	Boiler Flue Replacement	West	P&L
	Replace roof covering over		
Andersonstown Leisure Centre		West	P&L
Andersonstown Leisure Centre	Replace metal windows above	West	P&L
	nool	VVESI	FOL