

RPII ANNUAL PLAYGROUND INSPECTION REPORT



FALLS PLAY AREA BELFAST CITY COUNCIL 15th January 2020

This inspection was carried out by James Busby RPII Signed

ltem No.	Item Description	Inclusive for all Abilities Y/N	DDA/ Age Label	Quality Score	Compliance with BSEN 1176 Y/N	User Risk Assessment	Actions	s	ltem Priority	Safety Surface Compliance to BSEN 1177	Surfacing Risk Assessment	Actions	Surface Priority Works
1	Item: Basket Swing Manufacturer: Hags/SMP Label: Yes, 2014 Age Range: All Capacity: 4 Surfacing: Wet Pour 3+	Y	Y	4	Y	L		Replace end cap. Replace worn bushes.	2	Υ	L	N/A	5
2	Item: Seesaw Rocker Manufacturer: Kompan Label: Yes, 2014 Age Range: Junior Capacity: 4 Surfacing: Wet Pour 4+	Ν	Ν	8	Y	L	Replace age	e label.	4	Y	L	N/A	5
Overa	all Mean Score =			-									

*Quality Score

Excellent	= 10	Fair	= 5
Very Good	= 9	Insufficient	= 4
Good	= 8	Poor	= 3
Fairly Good	= 7	Very Poor	= 2
Sufficient	= 6	Extremely Poor	= 1

* Item Priority Action

Action within 1 hour (Contact Client)
 Action within 10 days
 Action within 28 days

4 Action within 3 months

5 Monitor

ltem No.	Item Description	Inclusive for all Abilities Y/N	DDA/ Age Label	Quality Score	Compliance with BSEN 1176 Y/N	User Risk Assessment	Actions	ltem Priority	Safety Surface Compliance to BSEN 1177	Surfacing Risk Assessment	Actions	Surface Priority Works
3	Item: 4 Seat Rocker Manufacturer: Kompan Label: Yes 2008 Age Range: Toddler Capacity: 4 Surfacing: Wet Pour 2 – 6	Ν	Y	8	Y	L	N/A	5	Y	L	N/A	5
4	Item: Toddler Multi Unit Unit Manufacturer: Sutcliffe Label: Yes Age Range: Toddler Capacity: 10 Surfacing: Wet Pour 2 - 6 Ú	Y	Y	5	Y	L	Replace binocular bearing.	3	Y	L	N/A	5

*Quality Score

Excellent	= 10	Fair	= 5
Very Good	= 9	Insufficient	= 4
Good	= 8	Poor	= 3
Fairly Good	= 7	Very Poor	= 2
Sufficient	= 6	Extremely Poor	= 1

* Item Priority Action

- Action within 1 hour (Contact Client)
 Action within 10 days
- 3 Action within 28 days
- 4 Action within 3 months
- 5 Monitor

ltem No.	Item Description	Inclusive for all Abilities Y/N	DDA/ Age Label	Quality Score	Compliance with BSEN 1176 Y/N	User Risk Assessment	Acti	ions	Item Priority	Safety Surface Compliance to BSEN 1177	Surfacing Risk Assessment	Actions	Surface Priority Works
5	Item: Giro Spiral Manufacturer: Proludic Label: Yes Age Range: Senior Capacity: 2 Surfacing: Wet Pour 6+	Ν	Y	4	Y	L		Tighten central rotating section and replace nut caps. Replace damaged seats.	2	Y	L	N/A	5
6	Item: Swings Manufacturer: Hags Label: Yes Age Range: All Capacity: 4 Surfacing: Wet Pour All Label: Wet Pour	Y	Y	4	Y	L		Monitor slight movement in frame legs.	5	Y	L	N/A	5
Overa	Overall Mean Score = 5					1		1					

*Quality Score

Excellent	= 10	Fair	= 5
Very Good	= 9	Insufficient	= 4
Good	= 8	Poor	= 3
Fairly Good	= 7	Very Poor	= 2
Sufficient	= 6	Extremely Poor	= 1

* Item Priority Action

Action within 1 hour (Contact Client)
 Action within 10 days
 Action within 28 days

4 Action within 3 months

5 Monitor

Site Name: Falls Park Play Area, Falls Road, Belfast, BT12 6AN

TYPE	GENERAL QUALITY CONDITION	ACTIONS	PRIORTY
Boundary Fencing	5	Remove cable ties. Replace post caps. Replace missing fixing.	2
Gates	2	Remove crush point.	2
Signage	10	N/A	5
Bins	8	N/A	5
Seating	8	N/A	5
Paths	2	Repair burnt areas of wetpour. Clean surface. Surface uneven at removed	3
	OVERALL MEAN SCORE: 5.8	unit – repair.	

ANCILLARY ITEMS

*Quality Score

Excellent	= 10	Fair	= 5
Very Good	= 9	Insufficient	= 4
Good	= 8	Poor	= 3
Fairly Good	= 7	Very Poor	= 2
Sufficient	= 6	Extremely Poor	= 1

* Item Priority Action

- Action within 1 hour (Contact Client)
 Action within 10 days
 Action within 28 days

- **4** Action within 3 months
- **5** Monitor